


Replacement of floors in cabins after water leak on a platform in the North Sea



CUSTOMER

Leading offshore operator
in the North Sea

THE PROJECT

A previous water leak has released the floor several places and resulted in rust in subfloor in two cabins on a platform in the North Sea. Our job was offshore inspection and installation of new floors.



WE ASSIST ON

- Technical inspection; offshore survey to clarify the floor condition after water leak including mould test etc.
- Project preparation; work prepare, permit preparation, purchasing and packing materials and tools.
- Project execution offshore;
 - Project management during project
 - Remove furnitures and demold existing floors
 - Grind and prime steel floor
 - Installatin of new subfloors and Amtico top floors.
 - Permit
 - Daily report to customer
- Final documentation and project close-out